

# s-BMS v6.15.1 release note

Please note that s-BMS v6.15 is bootload compatible with v6.1 – 6.14 releases.

v6.15.1 only contains changes to PC Software. No changes of firmware compared with the previous v6.15.

**Notice than v6.15 firmware should be used exclusively on a system, do not mix other firmware/software versions with v6.15.**

This release does not include the node locked version of the PC Tool “Diagnostic software”. Please see change list for additional information.

In case of any questions about the upgrading procedure, please do not hesitate to contact a Lithium Balance technician before attempting to upgrade the firmware.

The firmware version numbers for this release is:

<b>Unit:</b>	<b>Firmware version:</b>	<b>Boot loader version:</b>
BMCU	20000.0A.06.c.015	7
SUB	20000.0A.06.c.015	2, 1 or -1
LMU	20000.0A.06.c.015	2, 1 or -1
PC Tool	20000.6.15.1	Not applicable

s-BMS Diagnostic PC tool changes in this release:

BMS FOCUS	CORE BENEFIT	TECHNICAL DESCRIPTION
Bug fix	No execution blocking of Diagnostic PC tool	The previous v6.15 dongle protected version of the Diagnostic PC tool does not run after updating windows 10 to the latest version . When trying to start the application is windows reporting: “This app can't run on your PC. To find a version for your PC, check with the software publisher.” This new version fix the problem.

**September 6, 2019**

**On behalf of the R&D and support team at LITHIUM BALANCE**