

n-BMS release notes

n-BMS version 2.3.6



New in this release:

- ✓ Bugfix for n-CMU v2.0 temperature measurement.

ABOUT THIS RELEASE

The n-BMS v2.3.6 release includes changes for the MCU firmware and associated Creator PC support tool.

FIRMWARE FEATURES

The firmware function for temperature measurement in the n-CMU v2.0 hardware is changed in order to make correct temperature values. The previous firmware version embedded in Creator v2.3.5 had problems for correct temperature measurements.

RELEASE CONTENTS

1. File 'SETUP BMS Creator 2.3.6.exe' (BMS firmware embedded)
2. Manual n-BMS v2.3.5 (Previous manual reused, no functional changes)

On behalf of the Lithium Balance Support and R&D team

n-BMS 2.3.6 Release Notes – 15th February 2019



CONTACT

Lithium Balance A/S
Hassellunden 13
2765 - Smørum
DK - Denmark
+45 58 51 51 04
info@lithiumbalance.com
www.lithiumbalance.com